



VIDEO PIPELINE INSPECTION

**12715 Naomilawn Dr
Lakewood, WA**

Client Name:

Andrew Morrison

Inspection Date:

7/18/2018

Access Code:

miof

Inspector:

Chad Pauls

Report #:

180718A

Hydro Physics Contact:

PO Box 9159

Tacoma, WA 98490

Chad: (253) 651-7617

Clayton: (360) 628 1782

www.hydro-physics.co

clayton@hydro-physics.co

Visit <http://videos.hydro-physics.co/cabiahbimiof> to view a video of your sewer inspection.

Videos are typically available within 24 hours of the inspection!

Sewer Inspection Report

Description

Access is toilet Ended @ sewer main connection 134 Ft. Pipe material is cast to SDR (plastic) @ 10 Ft. 4 inch to 6inch SDR @ 108 Ft. Sewer main is plastic as well.

Observations

1. Monitoring Item :-> Roots in bottom of pipe 2 107 Ft; treat with side sewer herbicide; follow directions on package. Pipe appears to be working properly. Kitchen sink line not inspected

Visit <http://videos.hydro-physics.co> and enter the Inspection Date (7/18/2018) and Access Code (miof) to view a video of your sewer inspection.

Videos are typically available within 24 hours of the inspection!

Receipt

Client:
 Andrew Morrison

Sewer Inspection
7/18/2018

Inspection Address:
 12715 Naomilawn Dr, Lakewood, WA

Inspector:
 Chad Pauls

Description	Amount
Inspection with digital narrative report	\$215.00 (PAID)
Toilet Pull Fee	\$35.00 (PAID)
Balance Due	\$0.00

Paid CC

Monitoring Items - Roots in bottom of pipe 2 107 Ft; treat with side sewer herbicide; follow directions on package. Pipe appears to be working properly. Kitchen sink line not inspected

Notes - Access is toilet Ended @ sewer main connection 134 Ft. Pipe material is cast to SDR (plastic) @ 10 Ft. 4 inch to 6inch SDR @ 108 Ft. Sewer main is plastic as well.

Our service provides a video pipe inspection and documentation of pipe two (2) inches or greater inside diameter pipe, and helps detect for problem areas due to some of the following problems: broken lines, offset joints, crushed lines, major low areas in the pipe, debris in the pipe and other visually identifiable objects, obstructions, or serious problems in the pipe interiors. Hydro Physics provides its' customers with an unbiased video pipe inspection. Our cameras are used to get a different perspective (i.e. the inside of the pipe) but neither the equipment or the operator of this equipment are to be used to make engineering, repair, or replacement decisions without consulting a licensed plumber or engineering professional. Hydro Physics services help give you information, which would otherwise be inaccessible, to assist you in your decision making process.

Hydro Physics will locate areas of interest and approximate depths will be given. Because of the possibility that electrical or atmospheric disturbance has effected our equipment, no guarantee is made of the enact locations, depths or position of any potential problem area, Excavation of such an area is done at your risk and should only be done after consultation with an excavation expert. We do guarantee that we will use our best effort and workmanlike manner to provide you with the information you have requested. Your sole remedy for any dissatisfaction with our service is a refund of the price you have paid to Hydro Physics. Hydro Physics shall not be liable for any consequential damages.

Accepted By: _____ As Agent for Buyer (Customer) Date _____